

Title: Locomotive Inbound Inspection Report

Document Control No.: 10007 Revision: A

Release Document: 08/29/2014 Revision Date: 08/29/2014

Page: 1 of 4 Review Date: 04/03/2015

Model: SD40-2 Road No.: NREX 6486 Frame No.: 72642-6 Sold To: (conversion - on 45 frame)									
OEM Serial #: Date Built: Origin:									
Inspector: J. REININGER / J. McCLUSKY Location: MT. VERNON, IL									
BOTTOM INSPECTION									
Front: Short / Long Nose: High / Low MU: Yes / No MU Hose: Yes / No									
Dynamics: Yes / No Extended: Yes / No Grid(s) Condition: FAIR									
Bell: Yes / No Horn: Yes / No Frame Condition: FAIR									
Fuel Tank Size: 4000 GAL (?) Retention Tank: Yes / No Condition: INTERNAL									
Wheels: L1 <u>1 15/16"</u> L4 <u>2 3/8"</u> R1 <u>2"</u> R4 <u>2 3/8"</u>									
Size: L2 <u>2 1/16"</u> L5 <u>2 1/2"</u> R2 <u>2 1/8"</u> R5 <u>2 7/16"</u>									
L3 <u>2 1/16"</u> L6 <u>2 5/16"</u> R3 <u>2 1/16"</u> R6 <u>2 1/4"</u>									
Box Type: Hyatt / Timken (H / T)									
1. H/T 2. H/T 3. H/T 4. H/T 5. H/T 6. H/T									
T.M. Type 1. ALL D-78's 4. List Cut / Missing TM leads: N/A									
2. 3. Gear Ratio: 62:15 Brake Shoe Type: HFC									
Axle Drive Type & Condition: QUANTUM, FAIR									
Draft Gear Type & Condition: Front: 390, FAIR Rear: 390, FAIR									
Draft Gear Pocket Condition: Front: FAIR Rear: FAIR									
Coupler Type: Front: E Rear: E Self-Aligning: YES Condition: FAIR									
Pilot Type: REAR – 8" General Condition: FAIR TO POOR Plow Type: 36"									
Truck Type: 1. <u>HTC</u> 2. <u>HTC</u> Rigging Pin Type: 1 2									
Brake Cylinder: 1. High / Low 2. High / Low									
LONGHOOD INSPECTION									
Walkway Condition: FAIR Handrail Condition: FAIR TO POOR									
Engine Type: 16-645-E3B S/N: 80-C1-1106 EMD Block No. (From A Frame) 16E80A126 Bars Over: Yes / No?									
GE Engine: Block H'Number: MFG: Japstar Anleister BCI Other: #:									
Engine Overall Condition: FAIR TO POOR Internal / Bottom End Condition: FAIR									
Turbo P/N: 9525597-R S/N: QT022515 01 Condition: GD TO FR Diffusor Condition: FAIR									
Fuel Pump: Yes / No Pre-Heater: Yes / No Oil Cooler: Yes / No Starter: Yes / No									
Fuel Bypass Valve & Gauge: Yes / No Spark Arrestors: Yes / No Exhaust Leaks: Yes / No									
Spin-On Filters: Yes / No Load Regulator Style: LINEAR Defective Tag: Yes / No									
Radiators: In / Out Leaks: Yes / No Radiator Type: Solder Mech. Bond.									
Fire Extinguishers: YES Longhood: Yes / No Cab: Yes / No									
AC Cabinet: YES Fan Fuses: Yes / No 200 lb. Air Gauge: Yes / No									



Title: Locomotive Inbound Inspection Report

Document Control No.: 10007 Revision: A

Release Document: 08/29/2014 Revision Date: 08/29/2014

Page: 2 of 4 Review Date: 04/03/2015

Air Compressor Type: WBO Bas	se Style: H	IGH	Condition:	FAIR						
Air Filter Type / System:		Condition:	FAIR							
Air Filter Media Type: Baggie Paper -PL	EATED	Other:								
Air Braker Type / System: 26L		Condition:	GOOD TO FA	AIR						
EMD Main Gen./Alt. Type AR10A7 / D14	S/N:	79H1-1098	_ Condition:	FAIR						
EMD Aux. Generator Type: 18 KW	S/N:	CANNOT SEE	_ Condition:	CANNOT SEE						
GE AUXI. Model N/A	S/N:	N/A	_ Condition:	N/A						
GE EXCITER. Model: N/A	S/N:	N/A	_ Condition:	N/A						
A.G. Blower Wheel Type: DUAL		Condition:	FAIR							
D.B. Fan: YES Qty: 2 Size	e: <u>48"</u>	Blades: <u>10</u>	Ту	pe: FAB						
#1 Cool Fan: Size: 48" Blades:	9	Type: Cast	Fab	GE, ALCO						
#2 Cool Fan: Size: 48" Blades:	9	Type: Cast	Fab	Fan Drive Type						
#3 Cool Fan: Size: 48" Blades: _	8	Type: Cast	Fab	Eddy Current Direct Drive						
#4 Cool Fan: Size: N/A Blades:	N/A	Type: Cast	Fab	Condition: N/A						
Equipment Rack: Yes / No Type: Inertial Filters & Blower Motor: Yes / No										
Paint Color Condition: Carbody: BLUE/YLW- Eng. Room: GREY-POOR Cab: GREY-FAIR FAIR TO PR										
CAB / SHORT NOSE INSPECTION										
Cab Condition: Floor: FR TO PR Wall: FAIR Glass Meets FRA Req.: Yes / No Condition: FAIR										
Cab Lights: Yes / No Modules: Yes / No # Missing: N/A Air Brake Change Date: 2/19/15										
H.V. Cabinet: YES Wire Type: Exane Hyplon Gear Magnetic Pneumatic										
Evidence of Rewire? Yes / No Comments:										
Speedo Type: QUANTUM DIG. Heaters Water Electric Strip Seats 3 Arm Rest: *2 Yes / No										
Cab Cards: Yes / No (If YES, record available data) Event Recorder Equipped: Yes / No Type: QUANTUM Q1044B										
Toilet Type: PRIME SS Water Cooler Type:	V/A	Wipers: <u>5</u>		Visors: 2						
Batteries: In / Out Condition: FAIR				Style: 4-CELL						
Control Stand Type: AAR Round Cash Register / Pedestal Condition: FAIR										
Radio Equipped: Yes / No EOT:	Yes / No	Aleri	ter: Yes	/ No BUILT INTO SPEEDO						
Cab Signal: Yes / No Computer	Control:	Yes / No								



Locomotive Inbound Inspection Report

Document Control No.: 10007 Revision: Release Document: 08/29/2014 Revision Date: 08/29/2014

Page: 3 of Review Date: 04/03/2015

Additional Notes:



NO AFM PRESENT, NO REAR DITCH LIGHTS

BATTERY BOX FACE PANELS ARE BOLT-ON

2 DENTS IN FRONT WALKWAY FACE

FRONT CROSSOVER POST BENT OUT SOME

3" PLUS GAPS BETWEEN ALL MIDDLE STEP KICK PLATES & STEP WELLS

SHEATHING FOR R/S EFCO WIRING HAS HOLE WORN THROUGH IT

SOME MU VALVE HANDLES STICKING

REAR PILOT BENT SOME

RUSTING IN R/S SUBBASE FLOOR

1 OF L/S BATTERIES HAS 1" HOLE/CRACK IN TOP

SOME ELECTRICAL CABLES LAYING DISCONNECTED IN SHORTNOSE

SOME RUSTING AT BASES OF INTERIOR SHORTNOSE WALLS

RUSTING AT REAR MEC

HINGE/EARS MISSING FROM L/R SANDER PANEL(TAKE-OFF)

RUSTING AT TOP OF L/F STAIRWELL

CHECK CLEARANCE FOR STEP EDGES BETWEEN SWITCH AND MIDDLE STEPS - SEEMS TIGHT

**EXCESSIVE AMOUNTS OF OIL ON TOP OF CAB, DOWN SHORTNOSE, FRONT HALF OF LONGHOOD,

**WALKWAYS, AR10, FRONT LONGHOOD FLOOR & SUMP

	Title: Locomotive inbound inspection Report							
	Docum	ent C	Control I	No.:	: 10007	Revision:	Α	
	Release Document: 08/29/2014				Revision Date:	08/29/2014		
MOVING FORWARD	Page:	4	of	4		Review Date:	04/03/2015	

ATTACHED ADDITIONAL SHEETS IF NECESSARY.