

## NATIONAL RAILWAY LOCOMOTIVE INBOUND INSPECTION REPORT

QF-10007 REV 1

Model R	P-EU4	Road No.	963	Frame No	5586-29	Sold To	NREX			. — I
OEM Serial#	24882	Date Built	1959	Origin		<u>-</u>		_		
Inspector <u>T</u>	. Sharp			Location	Silvis, IL			Date	3/21/2013	
				ВОТ	TOM INSPE	CTION				
Front	Short		Nose		Low	MU	Yes		MU Hoses	YES
Dynamics		No	Extended		No	Grid(s)	Condition			
Bell		No	Horn		No	Frame	Condition			
Fuel Tank Size N	IA		Reter	ntion Tank		No	Condition			
Wheels L1_	2 9/16	L4	2 11/16	R1	2 9/16	R4	2 11/16	<u>.</u>		
SIZE L2_	1 7/8	L5		R2	1 7/8	R5		_		
L3_	2 11/16	L6		R3	2 11/16	R6		_		<u> </u>
Box TYPE	1: Hyatt	2: Hyatt	3: Hyattn	4: Hyatt	5: Hyatt	6: Hyatt				
Т.М. Туре	1	D77-78	4	D77-78	List cut / ı	missing TM	leads	NO		
!	2	D77-78	5		Gear Ratio	62:15	Brake	Shoe Type	COMP 14"	
	3	D77-78	6		Axle Drive	Type & Cond	NA			
Draft Gear Type	& Cond	Front	SWITCHER	₹	Rear	SWITCHE	R	-		<u> </u>
Draft Gear Pock	ket Cond	Front	OK		Rear	OK		-		
Coupler Ty	pe Front	F	Rear	F	Se	elf-aligning	yes	Condition	OK	
Pilot Type P	LATE ON	ILY	General	Condition	BENT			Plow Type	NO	•
Truck Type	1	GP	2	GP	Riggin	g Pin Type	1	CLASP	2	CLASP
Brake Cyl.	1	High		2	High	— —	. — —			<b></b>
				LONG	HOOD INSP	ECTION	. — —			
Walkway C	ondition	GOOD			Handrai	I Condition	GOOD			
i _										j
	,				_				,	
! :	,				_		•			
<u> </u>						_		_		
! !										
į								_		
; 1										
										•
<u> </u>										
: :			. <u>.</u>		_					
:										•
Air Brake Type/S	ystem	26L			Condition	GOOD				į
EMD Main Gen/A	lt. Type		S/N		Condition					
EMD Aux. Genera	ator Type	10KW-DC	S/N	A1666E52	Condition	GOOD				
!					_					ļ
i					_					- -
A.G Blower Whee	el Type:	Single			Condition	Good				•





				FANS			
		_		<del>-</del>			
<b>.</b>						<u> </u>	
ī		_		_		i	
<b>.</b> ■		_		_		1	
• •							
		_		-		i	
■ ■				_		L	
Ī		<del></del>		_			
I							
Paint Color/Condition	Carbody	BLACK/ GC	OOD			_	
			CAB/SHO	RT NOSE INSPE	CTION		
•		_		_			
					Air Brake ch	nange date	1/23/2003
■ ■						9	
			_		Gear		Magnetic
- 1							
Cab Cards YES	(If yes, rec	ord available	data)				
•							
	_			<del>-</del>			
<u>.</u>							
			ADDITIONA	L DEFECTS/COM	MENTS		
] -							
FRAME IS BENT AT FROM	NT LIFTING F	PADS					
<b>.</b>							
1							
_							
• •							
- 							
•							
<u> </u>							
1 -							
• •							
Ī							
•							
- -							
•							
i							



